

Oil Field Environmental Incident Summary

Incident: 20140427112455 **Date/Time of Notice:** 04/27/2014 11:24

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: BWL SWD 5201 11-3

Field Name: CAMP

Well File #: 90192

Date Incident: 4/27/2014 **Time Incident:** 04:30

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 101

Sec: 3

Qtr: NW NW

Location Description: sw spill, all contained within dike.

Submitted By: John M. Jochim

Received By:

Contact Person: John M. Jochim
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	110	Barrels	108	Barrels	108	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/4/2016

Clean Up Concluded: 5/2/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The sw was sucked up and soil will be picked up asap.

Wastes Disposal Location: Sw will be put back in tanks and soil disposed of at Trevisa.

Agencies Involved:

Updates

Date: 4/27/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.